

VÝTLAK - V1	
lom	X,Y
L-1	X = -826131.64 Y = -1084299.22
L-2	X = -826139.72 Y = -1084292.29
L-3	X = -826156.20 Y = -1084273.24
L-4	X = -826179.23 Y = -1084238.88
L-5	X = -826188.25 Y = -1084228.35
L-6	X = -826203.20 Y = -1084220.67
L-7	X = -826202.29 Y = -1084213.67
L-8	X = -826219.62 Y = -1084211.59
L-9	X = -826238.15 Y = -1084207.28
L-10	X = -826254.98 Y = -1084200.00
L-11	X = -826266.83 Y = -1084192.81
L-12	X = -826277.79 Y = -1084183.87
L-13	X = -826307.18 Y = -1084148.94
L-14	X = -826334.59 Y = -1084165.77
L-15	X = -826362.46 Y = -1084185.07
L-16	X = -826378.66 Y = -1084195.33
L-17	X = -826421.59 Y = -1084220.93
L-18	X = -826457.14 Y = -1084242.26
L-19	X = -826476.66 Y = -1084255.53
L-20	X = -826492.69 Y = -1084270.61
L-21	X = -826503.85 Y = -1084284.13
L-22	X = -826516.69 Y = -1084303.24
L-23	X = -826532.21 Y = -1084327.32
L-24	X = -826528.18 Y = -1084329.92
L-25	X = -826545.28 Y = -1084356.16
L-26	X = -826571.34 Y = -1084398.83
L-27	X = -826597.02 Y = -1084439.68
L-28	X = -826596.27 Y = -1084447.39
L-29	X = -826618.75 Y = -1084482.56
L-30	X = -826620.23 Y = -1084492.32
L-31	X = -826625.76 Y = -1084500.60
L-32	X = -826640.97 Y = -1084526.65
L-33	X = -826647.48 Y = -1084538.15
L-34	X = -826650.43 Y = -1084544.89
L-35	X = -826659.65 Y = -1084569.52
L-36	X = -826677.74 Y = -1084608.87
L-37	X = -826684.04 Y = -1084625.34
L-38	X = -826690.61 Y = -1084637.49
L-39	X = -826696.45 Y = -1084646.03
L-40	X = -826701.62 Y = -1084655.51
L-41	X = -826705.70 Y = -1084660.98
L-42	X = -826719.93 Y = -1084678.68
L-43	X = -826767.72 Y = -1084739.87

lom	X,Y
L-44	X = -826784.89 Y = -1084760.73
L-45	X = -826794.08 Y = -1084771.23
L-46	X = -826798.45 Y = -1084776.46
L-47	X = -826803.04 Y = -1084782.47
L-48	X = -826811.14 Y = -1084791.42
L-49	X = -826824.52 Y = -1084805.04
L-50	X = -826845.02 Y = -1084823.99
L-51	X = -826848.18 Y = -1084826.25
L-52	X = -826853.11 Y = -1084828.21
L-53	X = -826873.16 Y = -1084834.99
L-54	X = -826890.53 Y = -1084843.04
L-55	X = -826906.09 Y = -1084848.44
L-56	X = -826926.90 Y = -1084855.12
L-57	X = -826948.86 Y = -1084861.68
L-58	X = -826958.21 Y = -1084865.38
L-59	X = -826964.44 Y = -1084868.97
L-60	X = -826967.62 Y = -1084872.10
L-61	X = -826973.83 Y = -1084879.15
L-62	X = -826982.72 Y = -1084891.87
L-63	X = -826987.96 Y = -1084901.78
L-64	X = -826991.78 Y = -1084910.10
L-65	X = -826995.29 Y = -1084923.69

VÝTLAK - V1	
čisticí šachta	X,Y
ČŠ-1	X = -826226.00 Y = -1084210.11
ČŠ-2	X = -826345.59 Y = -1084173.39
ČŠ-3	X = -826472.42 Y = -1084252.64
ČŠ-4	X = -826554.42 Y = -1084371.13
ČŠ-5	X = -826619.41 Y = -1084486.94
ČŠ-6	X = -826682.83 Y = -1084622.19
ČŠ-7	X = -826770.58 Y = -1084743.34
ČŠ-8	X = -826876.44 Y = -1084836.51
ČŠ-9	X = -826966.36 Y = -1084870.64
N	X = -826990.65 Y = -1084925.49

VÝTLAK - V2	
lom	X,Y
L-1	X = -826217.55 Y = -1084132.85
L-2	X = -826228.86 Y = -1084112.89
L-3	X = -826239.55 Y = -1084090.96
L-4	X = -826243.96 Y = -1084072.61
L-5	X = -826245.25 Y = -1084067.24